Oil Field Environmental Incident Summary

Responsible Party: BTA OIL PRODUCERS, LLC **Well Operator:** BTA OIL PRODUCERS, LLC

Well Name: 20006 STATE 21-36H

Field Name: BEAVER CREEK Well File #: 15724

Date Incident:3/13/2016Time Incident:09:00Facility ID Number:County:GOLDEN VALLEYTwp:143Rng:103Sec:36Qtr:

Location Description: Disposal well/battery

Submitted By: Pam Inskeep Received By:

Contact Person: Pam Inskeep

104 SOUTH PECOS MIDLAND, TX 79701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 30 Barrels 30 Barrels

Other

Description of Other Released Contaminant:

N/A

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:None anticipated

Areal Extent:

All contained

Potential Environmental Impacts:

None anticipated.

Action Taken or Planned:

Water was vacuumed up by Nuverra and replaced in tank onsite. Alarm/pump system company will evaluate and reprogram the system as well as determine the cause for failure of the system.

Wastes Disposal Location: All water was vacuumed up and replaced in the tank onsite.

Agencies Involved:

Updates

Date: 3/14/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained within diking according to the report. NDIC retains oversight.